

0020U.S. DPT. OF THE INTEREST

OFFICE OF SURFACE MINING RECLAMATION AND ENFORCEMENT





74 ACH 3, 18 P				OORITI			
1. Permittee/Person GENWAL COAL CO., INC. 2. Address P. O. BOX 1201 3. City HUNTINGTON 5. Zip Code	OF OIL. GAS & MINING	9. Permit Number UT-015-032 11. Inspection Date 03/08/95 MM · DD · YY 14. Permit Status A 17. OSM Office # 020 20. M.S.H.A. ID #	12. Inspection Type C 15. Site Status AP 18. RSI # 21. State Code	10. Type a. Permit b. RA PP S 13. Joint Inspection Y Y/N 16. Facility Type B 19. Land Code F 22. County Code			
7. Operator il Different than Fernittee				015			
8. Mine Name		42-01715 49 015 23. AVS Permittee Entity ID Number 23b. State Office					
CRANDALL CANYON		108257	,				
24. Performance Standard Categories Codes: 1=Compliance, 2=Noncompliance, 3=Not Planned, 4=Not Started,5=Noncompliance Identified Elsewhere							
A. Administrative			ncompliance Idei . <u>1</u> Subsidence Coi				
1. 1 Mining within Valid Permit 2. 1 Mining within Bonded Area 3. 1 Terms & Conditions of Permit 4. 1 Liability Insurance 5. 1 Ownership and Control 6. 3 Temporary Cessation B. Hydrologic Balance 1. 2 Drainage Control 2. 1 Inspections & Certifications 3. 1 Siltation Structures 4. 1 Discharge Structures 5. 2 Diversions 6. 1 Effluent Limits 7. 1 Ground Water Monitoring 8. 1 Surface Water Monitoring 9. 1 Drainage Acid-Toxic Materials 10. 1 Impoundments 11. 1 Stream Buffer Zones C. Topsoil & Subsoil 1. 1 Removal 2. 1 Substitute Materials 3. 1 Storage and Protection 4. 4 Redistribution	2. 3 Surface Stabilize 3. 3 Placement 4. 3 Inspections and 5. 3 Impounding Structure G. Use of Explosives 1. 3 Blaster Certifica 2. 3 Distance Prohib 3. 3 Blast Survey/Sc 4. 3 Warnings & Rec 5. 3 Control of Adve	Is and gullies) J. J. J. J. J. J. J. J. J. J	Roads 1. 1 Road Constru 2. 1 Certification 3. 1 Drainage 4. 1 Surfacing and 5. 1 Reclamation Signs & Markers 1. 1 Signs 2. 1 Markers . 1 Distance Prohi Revegetation 1. 1 Vegetative Co 2. 1 Timing [. 4 Postmining La . Other	Maintenance bitions over nd Use			
a. Date of Last	Inspection Hours	27. Bonded Acres	28. Acr	es			
State Complete Inspection Frequency for previous 4 Calendar Qtrs. b. Number of required complete inspections c. Number of required partial inspections 8 Inspections 01/13/95 Number of complete inspections conducted Number of required partial inspections conducted 8 Inspections	a. Permit Review 8.5 b. Inspection Time 7.0 c. Travel Time 8.0 d. Report Writing	5.6 bb Pl	onded	a. Permitted 5.5 b. Disturbed (Estimated) Page 1 of 2 Revised July 1, 1993			

U. S. DOPT. OF THE INTEROR

OFFICE OF SURFACE MINING RECLAMATION AND ENFORCEMENT Mine-Site Evaluation Inspection Report

Permit Number	UT-015-032	Inspection Date	03/08/95		

29. Identified Violation Data.

For inspection types C (Complete Random Sample) and SC or SP (Complete or Partial In-depth Review), list all violations present during the current Federal inspection and all violations, cited or uncited, identified in the last State complete inspection report. For any other inspection type, including Federal program inspections, list only violations observed during the current inspection or subject of current Federal follow-up actions.

B Per. Std. Category	C Abated (Y/N)	D State Action	E Reason if Uncited	F Cause	1	H usness Impact	I OSM Action		J OSM Action Number	K Optional
A. Specific State Law/Regulations Violated: R645-301-742.110 Description: FAILURE TO DESIGN SED CNTRL TO MEET EFFLU							T EFFLUE			
1 B1	N	2		1	3	1	2	X95-0	020-190-001 V# 01	
A. Specific S	tate Law/R	egulations	Violated: R6	45-301-	742.312		_ Descr	iption:_ ra 11	LURE TO MAINTAIN DIVERSIONS	
2 B5	N	4		4	3	1	1		V#	
A. Specific S	tate Law/R	egulations	Violated:	·			_ Descr	iption:		·_
3									V#	
A. Specific S	tate Law/R	egulations	Violated:				_ Descr	iption:		· _
4									V#	
A. Specific S	tate Law/R	egulations	Violated:				_ Descr	iption:		
5									V#	
A. Specific S	tate Law/R	egulations	Violated:				Descr	iption:		
6									V#	
A. Specific S	tate Law/R	egulations	Violated:				Descr	iption:		
7									V#	
D. State Action 1) Existed on LSC 2) Existed on LSC Cited 3) Cited Prior to L Abatement Per 4) Occurred Since 5) N/A Federal P 6) N/A Permit De	CI, Cited 1) N CI, Not 2) P 3) N SCI, 4) W nding 5) V e LSCI 6) P Program 7) T efect 8) W	lot a Violation recluded by S lot Included un Varning Given iolation Not Refractice Allowe oo Minor to Ci	ider State Program in Lieu of a Citation ecognized d under Approved F te perator to Correct		 Permit Unusua Condition Unoffic Operate Neglige 	Defect al Weather ons ial Waiver or	1) None of 2) Likely 3) Occurr	Occurrence or Unlikely	Inspector's Signature THOMAS WRIGHT Inspector's Printed Name	31. OSM Inspector
H. Impact Damage Remain: 1) None or Minor 2) Moderate 3) Considerable Damage Extends 4) None or Minor 5) Moderate 6) Considerable Obstruction to E 7) None or Minor 8) Moderate 9) Considerable	Beyond the Ponting of			1) Def 2) TDI 3) NO 4) FT/ 5) IH- 6) ID- 7) Pre 8) Aba	ferred to Sta N Issued V Issued A-CO Issued CO Issued CO Issued viously Cite		ronmental Harr ger to Public) stement Pen	ding	Dated: 03/16/95 Reviewing Official: Review Date: Page 2	1D# 190 7,5 of 2 evised July 1, 1993

Minesite Inspection Narrative

Inspection Date March 8, 1995

Mine: Crandall Canyon

Company: Genwal Coal Company P.O. Box 1201 Emery, Utah 84501

Weather: sunny and cool

Comments

This was a complete random sample inspection. Pete Hess of the Utah Division of Oil, Gas and Mining (DOGM), was the state representative on this inspection. Randy Gainer of Genwal represented the company on the inspection. Permits and records were reviewed at the company office in the town of Huntington during the morning of 3/8/95.

The present permit for the Crandall Canyon Mine was issued to Genwall Coal Company on 3/4/94 and expires on 5/13/98.

A copy of the Surety Bond from Safeco that became effective on 9/21/93 for was on file. Liability insurance had been recently updated.

A copy of NPDES Permit UT0024368 that expires on 8/31/95 was on file. According to the permit there are two discharge points for the mine, one for the sediment pond and the other for mine water discharge. Surface and groundwater monitoring records were available.

The last annual certification of the sediment pond was done on 1/13/95. An as-built certification for the pond was done 4/2/92. The most recent quarterly inspection of the pond had been done during December of last year.

A mine identification sign was in place at the entrance to the facilities. Perimeter markers were in place but additional markers were needed where UD-11 extends east of the mine fan and on the downstream end of the sediment pond. Additional markers along diversion UD-11 were placed before the inspection was completed.

Minesite Inspection Narrative Page 2 of 3

An additional buffer zone marker and a perimeter marker below the pond should be put in place to delineate where the corner of the permit on the downstream side of the mine is. Because some markers were visible no enforcement action is warranted at this time. Pete Hess informed the company that these markers were needed during the inspection.

UD-11 is a pipe that passes undisturbed flow from the hillside above the mine to the east off the disturbed area. During this inspection 2 breaks in this pipe were identified. As a result Notice of Violation 95-46-1-1 was written by DOGM on the morning after the inspection. A copy was provided to me and according to Pete Hess a copy was sent by certified mail to Genwal.

According to page 7-51 of the approved mining and reclamation plan there are 8 SAEs used on this mine. SAE #2 is on the northwest side of the mine and consists of a pad that was constructed for a sub station and the access road for it. On page 7-52 paragraph 3 states that a sediment trap is used for drainage control and 12" inch culvert was installed to act as a spillway.

Paragraph 4 on page 7-52 states that the sediment trap was modeled using Sedimont II and the results showed that the peak effluent concentration of suspended sediment from the trap will be 2898 milligrams per liter. Also paragraph 4 states that the concentration is greater than the standard contained in the R645 rules.

This trap was viewed during the inspection of the site. At that time there was no water contained in the structure so no discharge was occurring that could be sampled for evaluation.

Because information contained in the permit indicates that discharge from the structure referred to as SAE #2 would not meet effluent limitations as required by Utah regulations R645-301-751, (which requires discharges of waters from disturbed areas to be in compliance with state and Federal water quality laws and regulations), a violation exists.

Representatives of DOGM indicated that they would not issue a Notice of Violation for this area because of DOGM policy so Ten Day Notice 95-020-190-001 1 of 1 has been issued to the state covering this structure.

Because of snow cover on slopes above the creek, the outslopes of the site and pond embankment could not be safely viewed. The discharge outlet of the pond was visible from the road above and no sign of discharge was seen. The surface of sediment pond for this site was frozen.

Minesite Inspection Narrative Page 3 of 3

The placement of trash in the dumpster for the site was such that additional material would overflow and if heavy wind blew in the canyon this trash could be blown off the site. DOGM's representative told the company that better housekeeping practices were needed. As the trash remained at the dumpster no enforcement action is warranted at this time.

A pile of gravel sized rock was stored adjacent to the Forest Service parking area. This parking area is not approved for storage of rock so none can be stored on the parking lot. During the closeout with the company mention was made of storage of material in this area. Because the material was adjacent to the parking area and not on it no enforcement action is required, however any placement of material on the parking area would constitute a violation.

Other than the above mentioned Ten Day Notice issued by OSM and Notice of Violation issued by DOGM no other action resulted from this inspection.